

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	13	"5666710"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 11:21
L2	0	1 and (cantilever)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 11:21
L3	11	1 and (sens\$5 detect\$5 transducer measur\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 11:48
L4	9	3 and (face)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 11:50
L5	856	(blind) near3 (fasten\$5 rivet tool). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 12:02
L6	58	5 and (front) near3 (end face). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 11:51
L7	16	6 and (piezo\$5 sens\$5 gauge detect\$5 transducer measur\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 12:02
L8	6547	(blind) near3 (fasten\$5 rivet tool)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 12:02
L9	4	8 and (piezo\$5 sens\$5 gauge detect\$5 transducer measur\$5) near3 (front) near3 (end face)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 12:24

L10	87	(piezo\$5 sens\$5 gauge detect\$5 transducer measur\$5) near3 (front) near3 (end face) near3 (blind fasten\$5 tool rivet)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 12:25
L11	35	10 and (compress\$5 deform\$5 bend\$5 squeez\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/26 12:26